



ecology and environment, inc.

111 WEST JACKSON BLVD., CHICAGO, ILLINOIS 60604, TEL. 312-663-9415
International Specialists in the Environment

EPA Region 5 Records Ctr.



261590

M E M O R A N D U M


DATE: October 8, 1986
TO: File
FROM: David Curnock *DC*
SUBJECT: Illinois/Chicago Paxton Sites

There are three sites listed on the U.S. EPA ERRIS List pertaining to the Paxton Landfills on the southeast side of Chicago, Illinois. These sites are Paxton (ILD096949816), 119th and Paxton (ILD981535669) and Paxton II (ILD981535651). The original Paxton site (ILD069498186) was tasked to Ecology and Environment/FIT (E&E/FIT) to perform a site inspection under TDD 05-8303-01F. Under a subsequent TDD 05-8512-03, the U.S. EPA assigned E&E/FIT the task of preparing Preliminary Assessments (PA) on two additional "Paxton" sites. These sites were 119th and Paxton (ILD981535669) and Paxton II (ILD981535651).

The 119th and Paxton PA covered only parcel 2 of the three parcels that make up the Paxton II facility. The Paxton II PA covered the remaining parcels 1 and 3 (see Figure 1). There are actually only two sites present, Paxton I and Paxton II.

A site inspection was performed by E&E/FIT in May of 1986, which encompassed both Paxton I and II facilities. Due to uncertainties of boundary locations between Paxton I and II it seemed feasible to combine these site activities. The inspection report submitted covers both the Paxton I and Paxton II areas but uses only the original Paxton identification number (ILD069498186).

The 119th and Paxton site and the Paxton II site do not require site inspections since they have already been taken into account by the previous inspection performed on May 10, 1986.



PAXTON II



PAXTON I

ecology and environment, inc. 111 WEST JACKSON BLVD., CHICAGO, ILLINOIS 60604, TEL. 312-663-9415			
TITLE SITE MAP		FIGURE # 1	
SITE PAXTON AREA		SCALE NA	
CITY CHICAGO		STATE ILLINOIS	
SOURCE		TDD # NA	
		DATE 10/8/86	
		REVISED ---	